

6/6/2025

Electronic Service Assistant

# W0VMR8607LB212390



|                   |                                      |                     |                                    |
|-------------------|--------------------------------------|---------------------|------------------------------------|
| Manufacturer      | Opel                                 |                     |                                    |
| Model             | Movano                               |                     |                                    |
| Package           | MOVANO KAWA 2.3TD<br>99KW            |                     |                                    |
| Engine            | C042445                              |                     |                                    |
| Model             | 05D05                                | Model Year          | 2020A                              |
| Package Code      | QJI1                                 | Registration Number | ODGH1077                           |
| Colour            | POLAR WHITE (GNY)                    | Registration Date   | 4/20/2020                          |
| Trim Option       | TRIM CLOTH PULSE (TACR)              | Retailer Code       | DE0509                             |
| Engine Code       | ENG-4 CYL 2.3L FAM D2<br>E06T2 (O4R) | Tires               | 225/65 R16C (112/110)T             |
| Transmission Code | TRANS-MAN 6 SPO/DR                   | Wheels              | 6.5Jx16                            |
| Code              | Option                               | Code                | Option                             |
| OBM               | SVM Upfitter #20 (XBBA)              | OBR                 | SVM Upfitter #24 (XBDB)            |
| 2L4               | RADIO<br>AM/FM/USB/Bluetooth         | 32X                 | TRIM COLOUR - COLOUR<br>CHARCOAL   |
| 3B8               | TRIM CLOTH PULSE                     | 5EE                 | EQUIPMENT CO2-<br>REDUCTION STEP 2 |
| 5PE               | PANEL TRIM-NONE LEVEL2<br>PART.      | 5VR                 | ACCESSORY SIDE<br>OBSTACLE DETECT  |
| 82I               | GREY-INTERIOR TRIM                   | 8W8                 | SEAT BENCH ROW 3<br>DELETE         |
| 8X6               | SEAT REAR - DELETE (2ND<br>POSN)     | A32                 | ELECTRIC FRONT<br>WINDOWS          |
| AA5               | WINDOW RR QTR DELETE                 | AE0                 | SEAT PASSENGER FRONT<br>BENCH      |
| AIS               | BREAKING POINT 2020 1/2<br>M.Y       | AJ3                 | AIRBAG DRIVER SIDE<br>ONLY         |
| AJQ               | WINDOW ALL TINTED                    | AX6                 | BULKHEAD WITHOUT<br>WINDOW         |
| AXZ               | VEHICLE TYPE<br>COMMERCIAL VEHICL    | B21                 | SEAT FRT BKT W/LUMB<br>SUP DRIVER  |
| B9J               | A4 STORAGE ON<br>DASHBOARD           | BSJ                 | DOOR RH WITHOUT<br>WINDOW          |
| BTC               | PANEL BODY SIDE LH W/O<br>WINDOW     | C32                 | REINFORCED HEATING<br>ELECTRIC     |
| C37               | HEATED FRNT SEATS                    | C3F                 | GVW RATING 7 700 LBS               |
| C47               | REAR WINDOW DELETE                   | C60                 | AIR CONDITIONING                   |
| CE1               | WIPER SYS MOISTURE<br>SENSITIVE      | CLA                 | LOCK REMOTE ALL DOORS<br>2 FUNCT   |
| CT3               | GERMANY-MANDATORY                    | CTG                 | RESTRAINT CARGO-TIE<br>DOWN FLOOR  |
| D6N               | DRIVER I.DISP.LANG.<br>GERMAN        | DAR                 | ARMREST FRONT SEAT                 |
| DJ8               | MIRRORS ELEC OP/HT<br>CONVEX         | EH8                 | WHEELBASE 170 INCH                 |
| FE0               | SUSP SYSTEM FRT & RR<br>ACTIVE       | FWD                 | CHASSIS FRONT WHEEL<br>DRIVE-FWD   |
| GNY               | POLAR WHITE                          | I20                 | ENGINEERING YEAR 2020              |

W0VMR8607LB212390

| Code | Option                         | Code | Option                         |
|------|--------------------------------|------|--------------------------------|
| J1W  | DOOR RR W/O WINDOW             | K13  | FILTER EXHAUST SYSTEM PARTICLE |
| K34  | CRUISE CONTROL                 | K69  | KEY ADDITIONAL IGNITION        |
| KC8  | POWER OUTLET TRUNK             | KR1  | REFRIGERANT AIR CONDITIONING   |
| KW6  | GENERATOR 185 AMP              | LHD  | LEFT HAND DRIVE                |
| M73  | TRANS-MAN 6 SPO/DR             | NC0  | EU-EQUIPMENT                   |
| NCV  | EMISSION SYSTEM EURO 6D-TEMP   | NDE  | EXHAUST SELECT CATALYTIC REDUC |
| NH1  | FUEL TANK 80L 21 GAL           | NRV  | TYRE TREAD ALL HIGHWAY         |
| O4R  | ENG-4 CYL 2.3L FAM D2 E06T2    | OMT  | GTE TRANSLATION                |
| OTM  | BODY LENGTH STD. REAR OVERHANG | P34  | FULL SIZE SPARE WHEEL          |
| P91  | COVER WHEEL CENTER             | PL5  | PERFORMANCE DECREASE LEVEL 1   |
| Q8D  | MUD FLAPS FRONT                | R04  | WHEEL CONFIGURATION RR SINGLE  |
| R15  | APPEARANCEPACK.CHROME INTERIOR | R22  | ROOF HEIGHT HIGH               |
| RIX  | SALES REGION EUROPE            | T7E  | LAMP SYS DAY RUNNING LIGH LED  |
| TACR | TRIM CLOTH PULSE               | TH6  | TACHOGRAPH NONE                |
| TH8  | GOVERNOR SPEED CONTROL NONE    | TIQ  | EFFECTIVE POINT CONTROL-PHASE2 |
| TNG  | PARTS PKG/ROAD COND. LEVEL 1   | TR6  | HEADLAMP LEVELLING DEVICE      |
| U18  | SPEEDOM. KM                    | UD7  | REAR PARKING SENSORS           |
| UTJ  | THEFT DETER. EL UNAUTH. ENTRY  | VF7  | BUMPER RR STEP - NONE          |
| W4Y  | GEARING CODE                   | WML  | VIN MODEL YEAR 2020            |
| XBBA | SIDE ANCHORAGE RAILS           | XBDB | Roof Fixing Rails 2x           |
| XFP  | FUEL ECONOMY EXTRA             | XICK | COMPOUND CONVERSION            |
| XR5  | POLLEN FILTER                  | XZ27 | LCV INDEX 27                   |
| YK8  | IDENT. EFFECTIVE POINT CONTROL | Z0F  | GERMANY EQUIPMENT ADDITIONAL   |
| Z86  | MARKET BRAND OPEL              |      |                                |

6/6/2025

Electronic Service Assistant

**W0VMR8607LB212390**

| Invoice           | Date              | Retailer      | Odometer          | Labour ID                                                                                                                                                                                     | Work Description                                                                                                                                                                                                                                                                                                                                                    |
|-------------------|-------------------|---------------|-------------------|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| <b>WVRG515655</b> | <b>6/12/2024</b>  | <b>DE0462</b> | <b>124,823 km</b> | <b>AV-HU 02<br/>TÜV<br/>AV-UVV 01</b>                                                                                                                                                         | <b>HAUPTUNTERSUCHUNG<br/>TÜV<br/>TÜV - GEBÜHREN<br/>UVV nach §57 Abs. 1 BGV<br/>D 29</b>                                                                                                                                                                                                                                                                            |
| <b>WVRG504163</b> | <b>2/13/2024</b>  | <b>DE0462</b> | <b>122,541 km</b> | <b>2450470<br/>2450470005<br/>2450560<br/>PF<br/>2420170<br/>2420170019</b>                                                                                                                   | <b>Seilzug Feststellbremse<br/>hinten ersetzen<br/>Ein zusätzliches<br/>Handbremsseil hinten<br/>ersetzen<br/>Austausch<br/>Seilausgleicher<br/>Feststellbremse<br/>Probefahrt durchgeführt<br/>Bremsbeläge hinten<br/>ersetzen<br/>Bremssscheibe hinten<br/>ersetzen - beide Seiten<br/>[N]</b>                                                                    |
| <b>WVRG497164</b> | <b>11/13/2023</b> | <b>DE0462</b> | <b>119,833 km</b> | <b>AV-DIAG<br/>4025942<br/>PF</b>                                                                                                                                                             | <b>Diagnose lt. MDI<br/>Diagnoseblatt<br/>Partikelfilter reinigen<br/>Probefahrt durchgeführt</b>                                                                                                                                                                                                                                                                   |
| <b>WVRG490059</b> | <b>8/18/2023</b>  | <b>DE0462</b> | <b>119,809 km</b> | <b>2070260</b>                                                                                                                                                                                | <b>Wischerblatt<br/>Windschutzscheibe<br/>ersetzen</b>                                                                                                                                                                                                                                                                                                              |
| <b>WVRG490066</b> | <b>8/18/2023</b>  | <b>DE0462</b> | <b>119,809 km</b> | <b>4022660</b>                                                                                                                                                                                | <b>Schlauch Ladeluftkühler<br/>Lufteinlass ersetzen</b>                                                                                                                                                                                                                                                                                                             |
| <b>WVRG490067</b> | <b>8/18/2023</b>  | <b>DE0462</b> | <b>119,809 km</b> | <b>4417169<br/>0800389<br/>4416040<br/>0801342<br/>PF</b>                                                                                                                                     | <b>Analyse Klimaanlage<br/>Dichtheitsprüfung<br/>Abhilfe:<br/>Kältemittel ablassen und<br/>auffüllen (mit Reparatur)<br/>Probefahrt durchgeführt</b>                                                                                                                                                                                                                |
| <b>WVRG482172</b> | <b>5/4/2023</b>   | <b>DE0462</b> | <b>117,802 km</b> | <b>9101908P<br/>AV-FC<br/>AV-DIAG<br/>2810075<br/>PF</b>                                                                                                                                      | <b>AdBlue auffüllen=<br/>Fehlercode<br/>auslesen/zurücksetzen<br/>Diagnose lt. MDI<br/>Diagnoseblatt<br/>Steuergerät Motor mit<br/>SPS neu programmieren<br/>Probefahrt durchgeführt</b>                                                                                                                                                                            |
| <b>INT0125435</b> | <b>4/18/2023</b>  | <b>DE0462</b> | <b>117,743 km</b> |                                                                                                                                                                                               |                                                                                                                                                                                                                                                                                                                                                                     |
| <b>WVRG480260</b> | <b>4/18/2023</b>  | <b>DE0462</b> | <b>117,743 km</b> | <b>0601033<br/>4020470<br/>0601033011<br/>2070260<br/>2043350<br/>7430220<br/>8070032<br/>8070032003<br/>2043510<br/>AV-DIAG<br/>4068290996<br/>4068290<br/>4050420<br/>PF<br/>4022660996</b> | <b>Inspektion nach 40000,<br/>80000, 120000 ... km<br/>Luftfiltereinsatz ersetzen<br/>Bremsflüssigkeitswechsel<br/>Wischerblatt<br/>Windschutzscheibe<br/>ersetzen<br/>Scheinwerfer-Glühbirne -<br/>Austausch - Rechte Seite<br/>Spurstange außen<br/>ersetzen - rechte Seite<br/>Spureinstellung<br/>vermessen<br/>Vorderradfluchtung<br/>einstellen (Vorspur)</b> |

6/6/2025

Electronic Service Assistant

**W0VMR8607LB212390**

| Invoice    | Date       | Retailer | Odometer   | Labour ID                                         | Work Description                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                               |
|------------|------------|----------|------------|---------------------------------------------------|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
|            |            |          |            | 4022660<br>4024720<br>4052410<br>SLM<br>AV-UVV 02 | Glühlampe<br>Positionsleuchte vorn<br>ersetzen -<br>Motor reinigen und<br>einpudern - Diagnose<br>Ölverlust<br>Diagnosezeit [D]<br>Undichtigkeit im Bereich<br>Turbolader Abgasrohr<br>zum DPF aus und<br>einbauen -<br>Abgasrohr vorne aus und<br>einbauen<br>Probefahrt durchgeführt<br>Diagnosezeit [D]<br>Schlauch Ladeluftkühler<br>Lufteinlass ersetzen<br>Austausch Kühler,<br>Abgasrückführung<br>Abgaskrümmern aus und<br>einbauen<br>abgerissene und Runde<br>Schrauben entfernen<br>UVV nach §57 Abs. 1 BGV<br>D 29 |
| WVRG473476 | 1/17/2023  | DE0462   | 115,918 km | AV-LMW<br>AV-DIREKT-                              | Abblendlicht Fahrerseite<br>ersetzen<br>Nau-Werkstattcheck =                                                                                                                                                                                                                                                                                                                                                                                                                                                                   |
| WVRG461702 | 9/9/2022   | DE0462   | 94,179 km  | AV-DIAG<br>2420150                                | Diagnose Bremssystem<br>Bremsbeläge vorne<br>ersetzen                                                                                                                                                                                                                                                                                                                                                                                                                                                                          |
| WVRG460555 | 8/24/2022  | DE0462   | 92,574 km  | 4022660996<br>4022660<br>0801419<br>SLM           | Diagnosezeit [D]<br>Schlauch Ladeluftkühler<br>Lufteinlass ersetzen<br>Kühlsystem - Lecksuche<br>Abdeckung<br>Kraftstoffverteilerleitung                                                                                                                                                                                                                                                                                                                                                                                       |
| WVRG458540 | 7/28/2022  | DE0462   | 90,242 km  | 4041510<br>AV-DIAG<br>AV-DIAG                     | Batterie ersetzen<br>Fehlerspeicher auslesen<br>Generator und Batterie<br>prüfen                                                                                                                                                                                                                                                                                                                                                                                                                                               |
| WVRG456730 | 7/4/2022   | DE0462   | 89,246 km  | 4417169<br>0801332<br>2070260                     | Analyse Klimaanlage<br>Kältemittel ablassen und<br>auffüllen (ohne<br>Reparatur<br>Wischerblatt<br>Windschutzscheibe<br>ersetzen                                                                                                                                                                                                                                                                                                                                                                                               |
| WVRG454735 | 6/7/2022   | DE0462   | 85,138 km  | AV-UVV 02<br>AV-AU T02<br>AV-HU 02                | UVV nach §57 Abs. 1 BGV<br>D 29<br>Vorführung zur<br>Abgasuntersuchung (AU)<br>HAUPTUNTERSUCHUNG<br>TÜV                                                                                                                                                                                                                                                                                                                                                                                                                        |
| 6120070    | 2/1/2022   | DE1158   | 77,345 km  | 4033180<br>4033180996                             | Standheizung ersetzen<br>Diagnosezeit [D]                                                                                                                                                                                                                                                                                                                                                                                                                                                                                      |
| 2114642    | 11/16/2021 | DE1158   | 73,512 km  | 0601033                                           | Inspektion nach 40000,<br>80000, 120000 ...                                                                                                                                                                                                                                                                                                                                                                                                                                                                                    |

W0VMR8607LB212390

| Invoice    | Date       | Retailer | Odometer  | Labour ID | Work Description                            |
|------------|------------|----------|-----------|-----------|---------------------------------------------|
| 2213695    | 8/31/2021  | DE1158   | 64,544 km | 2420761   | Bremsscheibe hinten ersetzen - beide Seiten |
| 2213696    | 8/31/2021  | DE1158   | 64,544 km | 2420761   | Bremsscheibe hinten ersetzen - beide Seiten |
| 2213543    | 8/20/2021  | DE1158   | 35,521 km | 0601033   | Inspektion nach 40000, 80000, 120000 ...    |
| 2213544    | 8/20/2021  | DE1158   | 35,521 km | 0601033   | Inspektion nach 40000, 80000, 120000 ...    |
| 6110295    | 6/8/2021   | DE1158   | 51,756 km | 4068330   | Ölrücklaufleitung Turbolader ersetzen       |
| 2112141    | 5/28/2021  | DE1158   | 51,756 km | 2420671   | Bremsscheibe vorn ersetzen - beide          |
| 2210406    | 2/1/2021   | DE1158   | 35,521 km | 0601033   | Inspektion nach 40000, 80000, 120000 ... km |
| 2210407    | 2/1/2021   | DE1158   | 35,521 km | 0601033   | Inspektion nach 40000, 80000, 120000 ... km |
| 2213498    | 2/1/2021   | DE1158   | 35,521 km | 0601033   | Inspektion nach 40000, 80000, 120000 ...    |
| 2213545    | 2/1/2021   | DE1158   | 35,521 km | 0601033   | Inspektion nach 40000, 80000, 120000 ...    |
| 2210366    | 1/28/2021  | DE1158   | 35,521 km | 0601033   | Inspektion nach 40000, 80000, 120000 ... km |
| WVRG227031 | 11/30/2020 | DE0621   | 99 km     | SLM       | Unfallabschluss                             |
| GM-Drive   | 4/20/2020  | DE0509   |           |           |                                             |