

Model: X3 XDRIV A  
Vehicle identification number: WBAUZ95080N090695  
Development code: G01  
Model code: UZ05  
Lead type: UZ01

#### Vehicle

### BMW X3 XDRIV A, 210KW

WBAUZ95080N090695




Development code G01  
Colour carbon-schwarz  
Actual integration level S15A-20-11-567  
Start of warranty 18 May 2021

Delivery stop

 Technical Campaigns are available.


#### Technical campaigns

Status	Campaign number	Description	Reservation
Open	10051960500	Rework lashing rail in luggage compartment  Delivery stop Local campaign number: RR	

#### Special information

There are no Campaigns for this vehicle.

#### Live Diagnosis

 There are no service solutions for Live Diagnosis.

#### Service contracts

No BSI contracts

#### Information on faults workshop/Service Consultation

There is no information on faults.

#### Navigation map

Installed map

Enabling code (subscription)

Latest navigation map  
included in subscription

Latest navigation map subject  
to charge

Road Map EUROPE Live 2020-2 (As of: 14 Aug 2024)	Enabling code valid for navigation maps with release date up to 31 Dec 2099 (SWID: 01559912).	Road Map EUROPE Live 2024-4	-
--	---	-----------------------------	---

---

## Vehicle details

---

Vehicle type	Passenger car
Brand	BMW
Model	X3 XDRIV A
Body	GEFZG
Vehicle identification number (last 7 digits)	N090695
Vehicle identification number (17 digits)	WBAUZ95080N090695
Development code	G01
Steering	LL
Engine	B57P
Engine number	60916321
Exhaust re-treatment	EURO6, WLTP, AP, P/CI, M, N1 I
Transmission	AUT
Transmission number	0466590WLD
Head unit serial number	HBB312M3770331
Drive	ALLR
Integration level, works	S15A-20-11-567
Production date	13 Mar 2021
Production plant	SUEDAFRIKA
Delivery date	29 Apr 2021
Delivering retailer	Niederlassung München, München, DE
National-market version	EUR
Paint code	416
Upholstery code	BWNL
Model code	UZ05
Basic type	UZ95
Lead type	UZ01

---

## Optional equipment

---

### Optional equipment ex works:

01AG Larger fuel tank  
01CA Selection of COP-relevant vehicles  
01CB CO2 equipment  
01CE Recuperation system  
0223 Adaptive suspension  
0230 Extra package, EU-specific  
0248 Steering wheel heater  
0258 Tyres with runflat properties

### Retrofitted optional equipment:























This vehicle has no retrofits.

02NH M Sport brake  
02NQ 21" light-al.w.V-sp.k.726l em.op.mix tyre  
02PA Locking wheel bolt  
02TB Sport automatic gearbox  
02VB Tyre pressure display  
02VG Performance Control  
02VL Variable sport steering  
0302 Alarm system  
0319 Integrated universal remote control  
0320 Deleted, model lettering  
0322 Comfort access system  
03AC Trailer coupling  
03DS BMW display key  
03KA Acoustic comfort glazing  
03MC Indiv.roofrailing,mirror-fin.Shadow Line  
0413 Luggage compartment net  
0417 Roller sun visor, rear door  
0420 Sun protection glazing  
0423 Floor mats velours  
0428 Warning triangle and first aid kit  
0430 Interior/outside mirror with auto dip  
0431 Interior mirror with automatic-dip  
0459 Seat adjustment, electric, with memory  
0461 Electric seat backrest adjustment, rear  
0481 Sports seat  
0488 Lumbar support, driver and passenger  
0493 Storage compartment package  
0494 Seat heating driver/passenger  
04K7 Interior trim alu.rhomb.w.accent strip  
04U0 Electroplat.cover/clip f.operat.elements  
04UR Ambient interior light  
0534 Automatic air conditioning  
0536 Auxiliary heating  
0548 Kilometre speedo  
0552 Adaptive LED headlight  
05A1 LED Fog lights  
05AC High-beam assistant  
05AL Active Protection  
05AT Driving Assistant Plus  
05DA Passenger airbag deactivation  
05DN Parking assistance system Plus  
0610 Head-up display  
0654 DAB tuner  
0688 Harman/Kardon surround sound system  
06AC Intelligent emergency call  
06AE Teleservices  
06AK Connected Drive Services  
06C4 Connected Package Professional  
06NW Telephony with wireless charging  
06U3 BMW Live operating area Professional  
06WD WLAN Hotspot  
0710 M Leather steering wheel  
0715 M Aerodynamics package  
0760 High gloss shadow line  
0775 Headlining anthracite  
07LF Modell M Sport  
07M9 M Shadow Line with expanded scope  
07R7 Innovation package  
0801 German version  
0851 Language version German  
0879 On-board literature, German  
08KA Oil service interval 24 mths / 30,000 km  
08R9 Refrigerant R1234yf  
08TF Active pedestrian protection  
08TR Decoding additional functions  
0925 Dummy-SALAPA  
09D5 Entertainment package de  
09D6 Fahrerlebnis package de  
09D7 Winterfreude package de  
A090 90 Ah AGM battery

**Note:** Permitted CAL ID/CVN combinations in EURO vehicles.

Control unit	Control unit class	CAL ID	CVN
DDE	DDE	412175FB	412175FB
DME1	DME	FD619C53	FD619C53

## Vehicle histories

Date	Type	Vehicle mileage	Retailer	Overview
12/08/2024	Key	115687 Km	04543	Key 1
			  	    
15000 03/2026	15000 03/2026		03/2026	03/2026
			03/2026	03/2028
				05/2026
12/08/2024	Key	115687 Km	04543	Key 1
			  	    
15000 03/2026	15000 03/2026		03/2026	03/2026
			03/2026	03/2028
				05/2026
12/08/2024	Repair	115688 Km	04543 ,	Job Job Job Job Job Job Job

— Job

Description:

Considered as a repeat visit No

Customer's own words

Fahrzeugüberprüfung im Rahmen der Annahme  
Flat rate unit | 00 52 054

Local

1 FRU

— Job

Description:

Considered as a repeat visit No

Customer's own words \*E CID ausgefallen -> keine Audioausgabe -> prüfen und Info an SB vor inst. -> Kulanz prüfen, O-Ton Mechaniker / Zu BA Pos.50:->BA nachvollziehbar. Bei aufstarten des, Infotainments ist Bildschirm kurz sichtbar - Profilübersicht. Danach, flackert Display und geht aus. Tonabgabe i.O. HU fährt somit korrekt, hoch. Lt. FS ist interner SG Fehler "Hintergrundbeleuchtung CID", vorhanden. Lt. TM CID defekt / ers.,

Performing vehicle test  
Flat rate unit | 00 00 006

4 FRU

Supporting the voltage of the vehicle electrical system/recharging the vehicle electrical system battery  
Flat rate unit | 61 21 528

1 FRU

— Job

**Description:**

Considered as a repeat visit No

**Customer's own words**

Füllstand Betriebsflüssigkeiten/Frost-Flat rate unit | NL00 50 0

Local

2 FRU

— Job

**Description:**

Considered as a repeat visit No

**Customer's own words**

Service Standard Fahrzeugpflege Part | IF00200

Local

1

— Job

**Description:**

Considered as a repeat visit No

**Customer's own words**

Ersatzfahrzeug (24 Stunden) Part | 0000160

Local

3

— Job

**Description:**

Considered as a repeat visit No

**Customer's own words** Central Information Display ersetzen,\*O-Ton Mechaniker / Zu BA Pos.50:->BA nachvollziehbar. Bei aufstarten des,Infotainments ist Bildschirm kurz sichtbar - Profilübersicht. Danach,flackert Display und geht aus. Tonabgabe i.O. HU fährt somit korrekt,hoch. Lt. FS ist interner SG Fehler "Hintergrundbeleuchtung CID",vorhanden. Lt. TM CID defekt / ers.,,

Replace Central Information Display Flat rate unit | 65 50 558

2 FRU

Central information display Part | 65505A065D5

1

— Job

**Description:**

Considered as a repeat visit No

**Customer's own words** Zu FSA festgestellt -> TRSVC / Rundumsicht SG hat einen,Programmierabbruch hinterlegt. Nach Rü. SB wird Fzg programmiert.,

Programming/encoding control unit(s) including deleting fault memories Flat rate unit | 61 00 730





4 FRU

— 12/07/2024 Key

113254 Km

04543

Key 1







— 12/07/2024 Service

113254 Km

04543  
Niederlassung  
Leipzig,  
Leipzig

Automatic



— 12/07/2024 Repair

113254 Km 04543 ,

Job  
Job  
Job  
Job  
Job  
Job

— Job

Description:

Considered as a repeat visit No

Customer's own words

Fahrzeugüberprüfung im Rahmen derAnnahme Flat rate unit I 00 52 054	Local	1 FRU
--	-------	-------

— Job

Description:

Considered as a repeat visit No

Customer's own words

Service - standard scope Flat rate unit I 00 00 105		2 FRU
--	--	-------

— Job

Description:

Considered as a repeat visit No

Customer's own words

Service, rear brakes Flat rate unit I 00 00 614		8 FRU
--	--	-------

Brake-pad paste Part I 83 19 2 158 851		2
---	--	---

Safety cleaner 2.0 Part I 83 19 2 364 762		10
--	--	----

Repair kit, brake pads asbestos-free Part I 34 21 6 890 353		1
--	--	---

Brake-pad sensor, rear Part I 34 35 6 870 350		1
--	--	---

— Job

Description:

Considered as a repeat visit No

Customer's own words

Füllstand Betriebsflüssigkeiten/Frost- s Flat rate unit I NL00 50 0	Local	2 FRU
--	-------	-------

— Job

Description:

Considered as a repeat visit No

Customer's own words

Service Standard Fahrzeugpflege  
Part I IF00200

Local























1

— Job

Description:

Considered as a repeat visit No

Customer's own words

11/07/2024	Key	113208 Km	04543	Remote KeyRead						
										
17000		17000						44000		
03/2026		03/2026		03/2026				03/2028	05/2026	
13/05/2024	Key	107457 Km	05842	Remote KeyRead						
										
23000		23000						48000	-12 1.6%	
03/2026		03/2026		03/2026				03/2028		
13/05/2024	Repair	107458 Km	04543 ,	Job						
				Job						
				Job						
				Job						
				Job						
				Job						
				Job						
				Job						

— Job

Description:

Considered as a repeat visit No

Customer's own words

Ersatzfahrzeug (24 Stunden) 10.05.-14.05  
Part I 0000160

Local

4

— Job

Description:

Considered as a repeat visit No

Customer's own words SM Einsatz--Reifenschaden vorn rechts--vermutlich Schlagloch---bitte,Felge vorn rechts prüfen und defekten Reifen ersetzen---Klärung da,Allrad wegen evtl. weiteren 3 Reifen ersetzen----  
Überprüfung,Unt  
erboden--auf Kundenwunsch keine Fahrwerksvermessung durchführen,

Vier Reifen ersetzen  
Flat rate unit I NL36 01 3 Local 29 FRU

Bridgestone ALENZA 001 RFT  
Part I 85 45 2 593 906 2

Bridgestone ALENZA 001 RFT  
Part I 85 45 2 593 907 2

Disc wheel, light alloy, Orbitgrey  
Part I 36 10 8 043 670 1

Repair kit, screw-type valve RDCi 1

## — Job

**Description:**

Considered as a repeat visit No

Customer's own words

## — Job

**Description:**

Considered as a repeat visit No

Customer's own words

## — Job

**Description:**

Considered as a repeat visit No

Customer's own words

§ Abgasuntersuchung mit OBD und Sonde Part I NL12159	Local	1
Vergütung gem. Nr. 6.4 der Anlagen VIIIb Part I NL12160	Local	1
Überprüfung nach § 29 STVZO Part I 0012159	Local	1

## — Job

**Description:**

Considered as a repeat visit No

**Customer's own words** O-Ton-Mechaniker: Hinweis: desweiteren wurde festgestellt dass AdBlue, an der Verbindungsschelle am Dosiermodul und an der Dichtung zwischen, Mischer und Abgasanlage austritt Verkrustungen sichtbar - Nach RS SB, nach Service Lösung DE SEL-SEL-P-11-20000813345099-02 instandgesetzt da, sicherheits- und umweltrelevant, SCR-Dosiermodul unterer Motorbereich aus - und einbauen/ersetzen, (reduziert da nur Dichtung zur Abgasanlage ersetzt wurde. Kühlsystem, Lüfterzarge verbindung oben blieben unberührt!),

Removing and installing or replacing mixer for exhaust system Flat rate unit I 18 31 640		3 FRU
Removing and installing/replacing the SCR metering module of the bottom engine compartment Flat rate unit I 11 78 650		4 FRU
V-band clamp Part I 18 30 8 590 002		1
Gasket Part I 18 30 8 595 104		1
Flat gasket Part I 18 30 8 474 428		1
Collar nut Part I 07 11 9 906 089		2

## — Job

**Description:**

Considered as a repeat visit No

Customer's own words



— Job

Description:

Considered as a repeat visit No


Customer's own words

— 27/03/2024 Key

103185 Km

04543

Key 1




— 27/03/2024 Service

103185 Km

04543

Automatic

Niederlassung  
Leipzig ,  
Leipzig



— 27/03/2024 Repair

103189 Km

04543

Job

Niederlassung  
Leipzig BMW  
AG, Leipzig

Job  
Job  
Job  
Job  
Job  
Job  
Job  
Job  
Job  
Job  
Job  
Job  
Job  
Job  
Job  
Job  
Job  
Job  
Job  
Job  
Job  
Job

— Job

Description:

Considered as a repeat visit No

Customer's own words

— Job

Description:

Considered as a repeat visit No

Customer's own words

Set of wiper blades  
Part I 61 61 7 469 820 1

---

Wiper blade  
Part I 61 62 7 407 273 1

---

— Job

Description:

Considered as a repeat visit No

Customer's own words

— Job

Description:

Considered as a repeat visit No

Customer's own words

— Job

Description:

Considered as a repeat visit No

Customer's own words

— Job

Description:

Considered as a repeat visit No

Customer's own words Füllstand Betriebsflüssigkeiten/Frost- schutzgehalt prüfen: ja ergänzen: ja,,

---

Füllstand Betriebsflüssigkeiten/Frost- s Local 1 FRU  
Flat rate unit I NL00 50 0

— Job

Description:

Considered as a repeat visit No

Customer's own words

— Job

Description:

Considered as a repeat visit No

Customer's own words

— Job

Description:

Considered as a repeat visit No

Customer's own words Frontkamera aus- und einbauen/ersetzen,,\*E Steinschlag,,,

---

Remove and install front camera 12 FRU  
Flat rate unit I 66 53 620

---

Surround view camera 1  
Part I 66535A0F6D7

---

— Job

Description:

Considered as a repeat visit No

**Customer's own words**

---

Service - standard scope  
Flat rate unit I 00 00 105 2 FRU

— Job

**Description:**

Considered as a repeat visit No

**Customer's own words**

---

Brake fluid service  
Flat rate unit I 00 00 618 4 FRU

---

Brake fluid DOT4 LV, low viscosity  
Part I 83 13 0 443 030 1

— Job

**Description:**

Considered as a repeat visit No

**Customer's own words**

---

Engine oil service  
Flat rate unit I 00 00 610 3 FRU

---

Set oil-filter element  
Part I 11 42 7 826 799 1

---

BMW Engine Oil LL04 0W30  
Part I 83 21 2 405 950 7

— Job

**Description:**

Considered as a repeat visit No

**Customer's own words**

---

Service fuel filter  
Flat rate unit I 00 00 604 5 FRU

---

Fuel filter cartridge  
Part I 13 32 8 591 019 1

---

Self-locking hex nut  
Part I 64 50 9 123 157 2

— Job

**Description:**

Considered as a repeat visit No

**Customer's own words**

---

Service - air filter element  
Flat rate unit I 00 00 602 4 FRU

---

Air filter element  
Part I 13 71 8 577 170 1

— Job

**Description:**

Considered as a repeat visit No

**Customer's own words**

---

Microfilter service Flat rate unit I 00 00 616		2 FRU
---	--	-------

---

Microfilter/activated Carbon container Part I 64 11 9 382 886		1
--	--	---

— Job

**Description:**

**Considered as a repeat visit** No

**Customer's own words** Festgestellte Mängel,-Felge vorn rechts und hinten rechts angefahren -> Info,-Halter Kabel  
Luftmassenmesser gebrochen -> Info,,

---

Service, vehicle check Flat rate unit I 00 00 624		6 FRU
--	--	-------

— Job

**Description:**

**Considered as a repeat visit** No

**Customer's own words**

---

Service, advisory consultation at vehicle Flat rate unit I 00 52 050		1 FRU
---	--	-------

— Job

**Description:**

**Considered as a repeat visit** No

**Customer's own words**

---

Service Standard Fahrzeugpflege Part I IF00200	Local	1
---	-------	---

— Job

**Description:**

**Considered as a repeat visit** No

**Customer's own words**

---

Motorraumpflege - Basiswäsche nicht inkl Part I 0099531	Local	1
--	-------	---

— Job

**Description:**

**Considered as a repeat visit** No

**Customer's own words**

---

Ersatzfahrzeug (24 Stunden) Part I 0000160	Local	1
---	-------	---

— Job

**Description:**

**Considered as a repeat visit** No

**Customer's own words**

---

Ersatzfahrzeug (24 Stunden) Part I 0000160	Local	1
---	-------	---

— Job

**Description:**


Considered as a repeat visit No

Customer's own words

29/02/2024 Key

100019 Km 04543


Remote KeyRead



11/09/2023 Key

80159 Km 04543

Key 1



11/09/2023 Service

80159 Km 04543

Manual

Niederlassung  
Leipzig,  
Leipzig



11/09/2023 Repair

80161 Km

04543  
Niederlassung  
Leipzig BMW  
AG, Leipzig

Job  
Job  
Job  
Job  
Job  
Job  
Job  
Job

Job

Description:

Considered as a repeat visit No

Customer's own words

Service - standard scope  
Flat rate unit I 00 00 105

2 FRU

Job

Description:

Considered as a repeat visit No

Customer's own words Hinweise:,-Schraube Unterboden an Hintzeschutzblech (nahe Endtopf rechts)lose ->,befestigt,

Engine oil service  
Flat rate unit I 00 00 610

3 FRU

Set oil-filter element  
Part I 11 42 7 826 799

1

BMW Engine Oil LL04 0W30  
Part I 83 21 2 405 950

7

battery  
Part I 66 12 6 912 985

1

Job

Description:

Considered as a repeat visit No

Customer's own words

Microfilter service Flat rate unit I 00 00 616		2 FRU
---	--	-------

Microfilter/activated Carbon container Part I 64 11 9 382 886		1
--	--	---

— Job

Description:

Considered as a repeat visit No

Customer's own words

Fahrzeugüberprüfung im Rahmen der Annahm Flat rate unit I 00 52 054	Local	0 FRU
--	-------	-------

— Job

Description:

Considered as a repeat visit No

Customer's own words Füllstand Betriebsflüssigkeiten/Frost- schutzgehalt prüfen: ja ergänzen,;nein,,

Füllstand Betriebsflüssigkeiten/Frost- s Flat rate unit I NL00 50 0	Local	1 FRU
--	-------	-------

— Job

Description:

Considered as a repeat visit No

Customer's own words

Motorraumpflege - Basiswäsche nicht inkl Part I 0099531	Local	1
--	-------	---

— Job

Description:

Considered as a repeat visit No

Customer's own words

— Job

Description:

Considered as a repeat visit No

Customer's own words




Ersatzfahrzeug (24 Stunden) Part I 0000160	Local	1
---	-------	---

— 30/08/2023 Key

77534 Km

04543





Remote KeyRead



— 25/05/2023 Key

62060 Km





Key 1



19/05/2023 Key

61073 Km

Key 1











19/05/2023 Service

61073 Km

04543  
Niederlassung  
Leipzig,  
Leipzig

Automatic



19/05/2023 Repair

61073 Km

04543  
Niederlassung  
Leipzig BMW  
AG, Leipzig

Job  
Job  
Job  
Job  
Job

Job

Description:

Considered as a repeat visit No

Customer's own words

Service - standard scope  
Flat rate unit | 00 00 105

2 FRU

Job

Description:

Considered as a repeat visit No

Customer's own words

Fahrzeugüberprüfung im Rahmen der Annahme  
Flat rate unit | 00 52 054

Local

1 FRU

Job

Description:

Considered as a repeat visit No

Customer's own words Nein,

Füllstand Betriebsflüssigkeiten/Frost-  
Flat rate unit | NL00 50 0

Local

2 FRU

Job

Description:

Considered as a repeat visit No

Customer's own words

Service, front brakes Flat rate unit   00 00 612	7 FRU
Brake pad wear sensor, front Part   34 35 6 870 351	1
Repair kit, brake pads asbestos-free Part   34 11 6 889 570	1
Safety cleaner 2.0 Part   83 19 2 364 762	10
Brake-pad paste Part   83 19 2 158 851	2

— Job

Description:

Considered as a repeat visit No

Customer's own words

— Job












Description:

Considered as a repeat visit No












Customer's own words

Service Standard Fahrzeugpflege Part   IF00200	Local	1
---	-------	---

— 10/05/2023 Key 59472 Km Remote KeyRead

 16000 03/2025	 16000 03/2025	 16000 03/2025	 38000 03/2027	 38000 03/2027	 38000 03/2027	 38000 03/2027	 38000 03/2027	 38000 03/2027	 38000 03/2027	 38000 03/2027
---	---	---	---	---	---	---	--	---	---	---

— 04/04/2023 Key 52625 Km Key 1

 30000 03/2025	 30000 03/2025	 30000 03/2025	 60000 03/2027	 60000 03/2027	 60000 03/2027	 60000 03/2027	 60000 03/2027	 60000 03/2027	 60000 03/2027	 60000 03/2027
---	---	---	---	---	---	---	--	---	---	---

— 04/04/2023 Repair 52672 Km 00104 Job  
Autohaus  
Hofmann  
GmbH,  
Ingolstadt

— Job

Description:

Considered as a repeat visit No

Customer's own words

Kostenlose Wagenoberwäsche mit Bürstenwaschanlage Flat rate unit   00 00 002	Local	2 FRU
24-hour return service Flat rate unit   00 99 310		1 FRU

— 29/03/2023 Key 52270 Km Key 1



-1200  
4.4 %  
05/2024

-1200  
05/2024

-1200  
05/2024

-1200  
05/2024

03/2024

03/2024

-1200  
2.2 %  
05/2024

05/2024

— 29/03/2023 Service

52270 Km

00104

Automatic

Autohaus  
Hofmann  
GmbH ,  
Ingolstadt

-1200  
05/2024

-1200  
05/2024

-1200  
05/2024

-1200  
05/2024

-1200  
05/2024

— 29/03/2023 Repair

52275 Km

00104

Job

Autohaus  
Hofmann  
GmbH ,  
Ingolstadt

Job  
Job  
Job  
Job  
Job  
Job  
Job  
Job  
Job  
Job

— Job

Description:

Considered as a repeat visit No

Customer's own words

Service - standard scope  
Flat rate unit I 00 00 105

2 FRU

battery  
Part I 66 12 6 912 985

1

— Job

Description:

Considered as a repeat visit No

Customer's own words

Service - air filter element  
Flat rate unit I 00 00 602

4 FRU

Air filter element  
Part I 13 71 8 577 170

1

— Job

Description:

Considered as a repeat visit No

Customer's own words

Service fuel filter  
Flat rate unit I 00 00 604

5 FRU

Fuel filter cartridge  
Part I 13 32 8 591 019

1

Self-locking hex nut  
Part I 64 50 9 123 157

2

— Job

**Description:**

Considered as a repeat visit No

**Customer's own words**

---

Engine oil service Flat rate unit I 00 00 610		3 FRU
--	--	-------

---

Original Engine Oil 0W30 Part I FT99 99 7 999 1	Local	7
--	-------	---

---

Set oil-filter element Part I 11 42 7 826 799		1
--	--	---

— Job

**Description:**

Considered as a repeat visit No

**Customer's own words**

---

Microfilter service Flat rate unit I 00 00 616		2 FRU
---	--	-------

---

Microfilter/activated Carbon container Part I 64 11 9 382 886		1
--	--	---

---

Vehicle interior filt.f.housing cleaner Part I 83 19 2 451 455		1
---	--	---

— Job

**Description:**

Considered as a repeat visit No

**Customer's own words**

---

Service, vehicle check Flat rate unit I 00 00 624		6 FRU
--	--	-------

---

— Job

**Description:**

Considered as a repeat visit No

**Customer's own words**

---

Quick Check Fahrwerk Flat rate unit I 32 99 009	Local	2 FRU
--	-------	-------

---

— Job

**Description:**

Considered as a repeat visit No

**Customer's own words**

---

Adjusting headlights Flat rate unit I 63 10 502		2 FRU
--	--	-------

---

— Job

**Description:**

Considered as a repeat visit No

**Customer's own words**

Replace left and right wiper blade  
Flat rate unit I 61 61 541 1 FRU

Set of wiper blades  
Part I 61 61 7 469 820 1

— Job

Description:

Considered as a repeat visit No

Customer's own words

Replacing the wiper blade for the rear wiper  
Flat rate unit I 61 62 520 1 FRU

Wiper blade  
Part I 61 62 7 407 273 1

— Job

Description:

Considered as a repeat visit No

Customer's own words

(Annual) vehicle inspection within framework of DGUV Regulation 70  
Flat rate unit I 00 12 170 6 FRU

— Job












Description:

Considered as a repeat visit No












Customer's own words

Mietfahrzeug X5 R-HO201 Nutzung: 29.03.2023 / SZ 00000000 Local 1 FRU  
Flat rate unit I 99 99 999











07/02/2023 Key 48064 Km Remote KeyRead

 3200 05/2024	 3200 05/2024	 3200 05/2024	 3200 05/2024		 03/2024	 03/2024		 05/2024	 05/2024	
--	--	--	--	---	--	--	--	--	--	---

28/12/2022 Key 44242 Km Key 1

 8000 05/2024	 8000 05/2024	 8000 05/2024	 8000 05/2024		 03/2024	 03/2024	 -700 1.6%	 8000 05/2024	 05/2024	
--	--	--	--	---	--	--	--	--	--	---

28/12/2022 Service 44242 Km 00104 Automatic  
Autohaus Hofmann GmbH, Ingolstadt

 8000	 8000	 8000	 8000	 0	 0	 0	 -700 ✓	 8000	 0
---	---	---	---	--	--	--	---	---	--

28/12/2022 Repair 44242 Km 00104 Job Job  
Autohaus

— Job

Description:

Considered as a repeat visit No

Customer's own words

Service - standard scope  
 Flat rate unit I 00 00 105 2 FRU

— Job

Description:

Considered as a repeat visit No

Customer's own words

Service, rear brakes  
 Flat rate unit I 00 00 614 12 FRU

REINIGER / FETT Local 2  
 Part I 99 99 9 999 000

Repair kit, brake pads asbestos-free 1  
 Part I 34 21 6 890 353

Brake-pad sensor, rear 1  
 Part I 34 35 6 870 350

— Job

Description:


Considered as a repeat visit No

Customer's own words

Kostenlose Wagenoberwäsche mit Bürstenwaschanlage Local 2 FRU  
 Flat rate unit I 00 00 002

— 03/05/2022 Key


25781 Km 00104 Key 1



— 03/05/2022 Service

25781 Km 00104 Automatic

Autohaus  
 Hofmann  
 GmbH,  
 Ingolstadt



— 03/05/2022 Repair

25781 Km 00104 Job  
 Autohaus Job  
 Hofmann Job  
 GmbH, Job  
 Ingolstadt Job  
 Job

— Job

**Description:**

**Considered as a repeat visit** No

**Customer's own words**

---

Hochglanzpolitur ** Flat rate unit I 00 99 460	Local	15 FRU
---	-------	--------

---

Cleaning engine and engine compartment Flat rate unit I 00 11 359		4 FRU
--	--	-------

---

Removing dents without painting Flat rate unit I 41 99 010		5 FRU
---	--	-------

— Job

**Description:**

**Considered as a repeat visit** No

**Customer's own words**

---

Service - standard scope Flat rate unit I 00 00 105		2 FRU
--	--	-------

— Job

**Description:**

**Considered as a repeat visit** No

**Customer's own words**

---

Engine oil service Flat rate unit I 00 00 610		6 FRU
--	--	-------

---

Original Engine Oil 0W30 Part I FT99 99 7 999 1	Local	7
--	-------	---

---

Set oil-filter element Part I 11 42 7 826 799		1
--	--	---

— Job

**Description:**

**Considered as a repeat visit** No

**Customer's own words**

---

Microfilter service Flat rate unit I 00 00 616		2 FRU
---	--	-------

---

Microfilter/activated Carbon container Part I 64 11 9 382 886		1
--	--	---

---

Vehicle interior filt.f.housing cleaner Part I 83 19 2 451 455		1
---	--	---

— Job

**Description:**

**Considered as a repeat visit** No

**Customer's own words**

---

Service, advisory consultation at vehicle Flat rate unit I 00 52 050		0 FRU
---	--	-------

— Job











**Description:**

Considered as a repeat visit No


Customer's own words

Ersatzfahrzeug Mini Cooper IN-HA406 Businesscard geb.E Z 00000000Local 1 FRU  
Flat rate unit | 99 99 999

— 08/04/2022 Key 22694 Km 00104 Remote KeyRead

 2000 03/2023	 2000 03/2023	 2000 323	 03/2024	 03/2024	 683	 03/2025	 28000 03/2025	 05/2024	 05/2024
--	--	--	--	--	--	--	--	--	--

— 20/05/2021 Service 22 Km 04107 BMW AG NL München, München Manual


0
05/2021
✓

— 18/05/2021 Repair 5 Km 04107 Niederlassung München BMW AG, München Job Job

— Job

**Description:**

Considered as a repeat visit No

Customer's own words

— Job

**Description:**

Considered as a repeat visit No

Customer's own words Kostenlose Übergabedurchsicht,-Anzahl der Schlüssel/Ladekabel prüfen / notieren,( 1 )  
Funkschlüssel ( )Key Card wenn vorhanden aktivieren,( 1 ) Display Schlüssel mit separaten ( 1 )  
Metallschlüssel,-3  
L Scheibenreiniger erg. (aber nicht zu buchen),- Abschleppöse prüfen (+Gewindedurchmesser),,

Navigation-Freischaltcode abfragen und e Local 1 FRU  
Flat rate unit | AZ65 00 2

Kennzeichenhalter hinten montieren (BD) Local 1 FRU  
Flat rate unit | AZ00 20 0

Free pre-delivery check 9 FRU  
Flat rate unit | 00 00 009