




Audi

VIN-код: WAUZZZF40LA079595 Дизельне паливо

Згенеровано 06/11/2025



Сканувати й отримати повний звіт

Тип

✓ Виглядає нормально

Пробіг

✓ Виглядає нормально

Юридичний статус

✓ Виглядає нормально

Пошкодження

✓ Виглядає нормально

+36 Джерела даних
Ми перевірили 900+ джерел даних у 40 країнах

Тип

Транспортний засіб застосовувався як таксі, прокатний чи інший службовий ТЗ? Примітка: такі ТЗ можуть бути в гіршому стані, ніж зазвичай!

✓

Проблем не знайдено

Немає записів про використання ТЗ нестандартним чином

Результати перевірки:

- Таксі

✓ Записи не знайдені

 Немає доказів використання як таксі
- Перевезення

✓ Записи не знайдені

 Немає доказів використання як ТЗ для перевезень
- Прокатний

✓ Записи не знайдені

 Немає доказів використання як прокатного ТЗ
- Поліція

✓ Записи не знайдені

 Немає доказів використання поліцією
- Демонстраційний

✓ Записи не знайдені

 Немає доказів використання як демонстраційного транспортного засобу
- ТЗ школи водіння

✓ Записи не знайдені

 Немає доказів використання як ТЗ в школі водіння

Викрадення

Транспортний засіб наразі позначений як викрадений? Викрадався в минулому? Був знайдений?

✓

Проблем не знайдено

Ми не знайшли записів про викрадення транспортного засобу.

Примітка

Перевірку по поліцейській базі даних про викрадені автомобілі виконано в 11 країнах: +5

Ось що ми перевірили:



Наразі розшукується як викрадений

✓ Записи не знайдені



Викрадений в минулому

✓ Записи не знайдені

Записи про викрадення транспортного засобу не знайдені.

База даних поліції щодо викрадених транспортних засобів, **перевірку завершено:**

Італія Угорщина Румунія Чехія Словенія Словаччина Литва Сполучені Штати Канада
 Швеція Данія


Пробіг

Чи є ознаки скручування або розбіжності пробігу?



Примітка

- Останній відомий пробіг: 137 447 км
- Знайдено записів пробігу: 7



Дані одометра	
10.2020	12 км
04.2021	10 216 км
12.2021	27 650 км
10.2022	58 936 км
06.2023	87 735 км

Дані одометра	
04.2024	116 566 км
10.2024	137 447 км

Юридичний статус

Транспортний засіб пройшов техогляд? Чи має відмітку про здачу в утиль?

✓ Проблем не знайдено
Дані про юридичний статус транспортного засобу не знайдені

Юридичні

✓= Техогляд ✓ Записи не знайдені Записи про техогляд не знайдені

↺↻ Брухт ✓ Записи не знайдені Немає запису про позначення транспортного засобу як утилізованого

Пошкодження

Цей розділ допоможе зрозуміти, чи був транспортний засіб пошкоджений або оглянутий щодо пошкоджень, а також чи було складено кошторис (за наявності).

✓ Проблем не знайдено

Записи про пошкодження



Можливі окремі неточності, особливо під час перевірки старих транспортних засобів. Підпільні ремонтні майстерні можуть незаконно приховувати дефекти чи пошкодження, ніде не фіксуючи їх наявність. Часом можлива навіть підміна VIN-номерів. У нас є різні методи виявлення таких порушень, але 100% гарантію дати неможливо.

Стихійні лиха

Чи зафіксовано місцезнаходження транспортного засобу в зоні стихійного лиха?

-  **Проблем не знайдено**
Даних про перебування цього транспортного засобу в зоні стихійного лиха не зафіксовано

Специфікації та обладнання

Які специфікації та яке обладнання зареєстровані для цього транспортного засобу?

-  **Примітка**
Перевірте, чи специфікації та комплектація транспортного засобу відповідають фактам, зазначеним продавцем.

Ідентифікаційний код і технічні характеристики

-  **Марка**
Audi
-  **Тип кузова**
Вантажопасажирський
-  **Рік моделі**
2020
-  **Об'єм силового агрегата**
2 л
-  **Потужність силового агрегата**
120 кВт (161 к. с.)
-  **Тип палива**
Дизельне паливо
-  **Тип трансмісії**
Автоматична
-  **Тип приводу**
Передній привід



Кількість дверей

2



Розміщення керма

Лівостороннє керування



Кількість циліндрів

4



Код двигуна

DEZE

Обладнання

Як отримано від виробника

04A

BASIC

0F3

FUEL SYSTEM FOR DIESEL ENGINE

0G7

TIPTRONIC

0K4

HYBRID PROPULSION SYSTEM I-HEV

0M1

FUEL TANK

0RZ

WITHOUT IGNITION/STARTER SWITCH LOCKING
SYSTEM, WITHOUT STEERING LOCK

0UA

WITHOUT SPECIAL COLOR TRIM

0Y1

STANDARD CLIMATIC ZONES

1BL

SUSPENSION/SHOCK ABSORP. (CLOSED-LOOP)

1EX

SPECIAL IDENTIFICATION PLATE FOR EC FOR M1
PASSENGER VEHICLE

0C0

STANDARD

0FA

STANDARD MANUFACTURING SEQUENCE

0JJ

WEIGHT CATEGORY FRONT AXLE WEIGHT RANGE 9

0LW

WITH SPECIAL PLATES/LABELS/ SAFETY
CERTIFICATES FOR GERMANY

0P0

REAR EXHAUST TAILPIPE (STANDARD)

0TD

FLOOR MATS IN FRONT AND REAR

0VC

INFORMATION KIT IN GERMAN

0YJ

WEIGHT RANGE 9 INSTALLATION CONTROL ONLY, NO
REQUIREMENT FORECAST

1D4

TRAILER HITCH, MANUALLY SWIVELING

1G5

SPACE-SAVING SPARE WHEEL, SAME SIZE (SAME
ROLLING CIRCUMFERENCE) AS ORIGINALEQUIPMENT
TIRES

1KD

DISK BRAKES IN REAR

1PD

WHEEL BOLTS WITH ANTI-THEFT PROTECTION
(UNLOCKABLE)

1SA

WITHOUT ADDITIONAL FRONT UNDERBODY GUARD

1VG

INSTALLATION PARTS FOR FOUR-CYLINDER ENGINE

1XW

LEATHER-WRAPPED MULTIFUNCTION SPORTS
STEERING WHEEL

2F0

WITHOUT LOCKING AND STARTING SYSTEMS

2H9

DRIVE SELECT

2KR

LABELS/PLATES IN ENGLISH AND GERMAN

2Z0

ELIMINATION OF MODEL DESIGNATION

3FA

WITHOUT ROOF INSERT (STANDARD ROOF)

3GD

PLANE REAR CARGO AREA

3L4

POWER SEAT ADJUSTMENT FOR BOTH FRONT SEATS,
DRIVER SEAT WITH MEMORY FEATURE

3NT

REAR SEAT BENCH UNSPLIT, BACKREST SPLIT
FOLDING (THREE PIECES) WITH CENTER ARMREST

3Y4

ROLL-UP SUNSHADE FOR REAR SIDE WINDOWS

4D0

WITHOUT SEAT VENTILATION/MASSAGE SEAT

4F2

CENTRAL LOCKING SYSTEM "KEYLESS ENTRY"

1LA

DISK BRAKES IN FRONT

1S1

TOOL KIT AND JACK

1T3

FIRST AID KIT WITH WARNING TRIANGLE

1X0

FRONT WHEEL DRIVE

1Z0

INITIAL STANDARD FUEL FILLING

2G5

FILLER NECK MODULE 1 WITHOUT INSERT

2K1

REINFORCED BUMPERS

2WA

WITHOUT ADDITIONAL TIRES

3B3

CHILD SEAT ANCHOR

3G0

WITHOUT CHILD SEAT ANCHOR FRONT (ISOFIX)

3H0

WITHOUT BACKREST RELEASE FOR FRONT SEATS

3M3

PASSENGER CAR DESIGN

3S1

BRIGHT ROOF RAILS

4A3

SEAT HEATER FOR FRONT SEATS SEPARATELY
CONTROLLED

4E7

TAILGATE/TRUNK LID POWER CLOSING

4GR

LAMINATED WINDSHIELD, HEATED

4H3

MANUAL CHILD SAFETY LOCK

4L6

BREAKAWAY INTERIOR REARVIEW MIRROR, AUTO-DIMMING

4X4

SIDE AIRBAG IN FRONT AND REAR WITH CURTAIN AIRBAG

5A8

LUGGAGE COMPARTMENT LINING (DESIGN 2)

5D1

CARRIER FREQUENCY 433.92 MHZ-434.42 MHZ

5K5

TRANSIT COATING FILM WITH ADDITIONAL TRANSPORT PROTECTION MEASURES

5SL

LEFT EXTERIOR MIRROR: ASPHERICAL

5XF

SUN VISORS ON DRIVER AND FRONT PASSENGERSIDE, EXTRACTABLE

6A0

WITHOUT FIRE EXTINGUISHER

6EA

WITHOUT ADDITIONAL SIDE BODY COVERS (STONE GUARD)

6FA

COMPONENTS WITHOUT SPECIAL SURFACE APPEARANCE

6I1

LANE KEEPING SYSTEM

6K8

PRE SENSE CITY WITHOUT PRE CARE

6SJ

LUGGAGE COMPARTMENT FLOOR COVERING, REVERSIBLE MAT (RUBBER/FABRIC)

6V1

REAR TRIM PANEL (ECE)

4KC

SIDE AND REAR WINDOWS IN HEAT-INSULATINGGLASS

4UF

DRIVER AND FRONT PASSENGER AIRBAG WITH FRONT PASSENGER AIRBAG DEACTIVATION

4ZB

BRIGHT MOLDINGS

5C0

WITHOUT SPECIAL BODY MEASURES

5J0

WITHOUT REAR SPOILER

5L0

WITHOUT FRONT SPOILER

5TG

DECORATIVE ALUMINUM INSERTS, DULLING

5ZC

HEAD RESTRAINTS FOR FRONT SEATS (X-ADJUSTMENT)

6E3

CENTER ARMREST IN FRONT

6F7

EMBLEMS

6H0

"BASIC"

6JD

BODY-COLORED DOOR HANDLES

6NQ

STANDARD MOLDED HEADLINER

6TS

RIGHT EXTERIOR MIRROR, ASPHERICAL, LARGE VIEWING FIELD

6W6

FRONT LICENSE PLATE CARRIER

6XL

EXTERIOR MIRRORS WITH MEMORY FEATURE, AUTO-DIMMING, POWER-FOLDING/ADJUSTABLE/HEATED

7AL

ANTI-THEFT ALARM SYSTEM, INTERIOR MONITORING, BACKUP HORN, AND TOWING PROTECTION

7G0

WITHOUT PREPARATION FOR VTS (VEHICLE TRACKING SYSTEM)

7IA

VEHICLE CLASS DIFFERENTIATION 8W0/8WA

7L8

START/STOP SYSTEM WITH REGENERATIVE BRAKING

7UG

NAVIGATION SYSTEM - HIGH

7X5

PARK ASSIST

8G4

MATRIX BEAM

8IY

LED HEADLAMPS WITH LENS

8T8

ADAPTIVE CRUISE CONTROL (WITH "FOLLOW-TO-STOP") AND SPEED LIMITER

8Y1

TWO-TONE HORN

9AQ

AIR CONDITIONING SYSTEM PLUS

9JD

SMOKER'S PACKAGE, ASHTRAY IN FRONT

9M0

WITHOUT AUXILIARY HEATER/FUEL-FIRED PARKING HEATER

9S9

.

9WC

WITHOUT "MULTIMEDIA" IN VEHICLE

6Y1

CRUISE CONTROL WARNING SYSTEM

7E6

ELECTRIC AUXILIARY AIR HEATER

7HA

WITHOUT LEATHER

7K1

DIRECT TIRE PRESSURE MONITORING SYSTEM

7S0

WITHOUT WIND DEFLECTOR

7W3

WITH EXTENDED SAFETY SYSTEM (PROACTIVE PASSENGER PROTECTION SYSTEM, BASIC AND REAR)

7Y1

LANE CHANGE ASSIST

8I6

LUMBAR SUPPORT, PNEUMATICALLY ADJUSTABLE

8K4

SEPARATE DAYTIME RUNNING LIGHTS -- NAR --

8X1

HEADLAMP WASHER SYSTEM

8Z5

NOT HOT COUNTRY

9G7

BELT-DRIVEN STARTER ALTERNATOR 12 V 110-180 A

9K0

WITHOUT AIRSCARF

9P6

SEAT BELT REMINDER, ELECTRIC CONTACT IN BUCKLE

9VD

SPEAKER (ACTIVE)

9ZE

COMFORT TELEPHONE SYSTEM

A00

NO SELF-COLLECTION

A60

CATEGORY 0

AQ0

STANDARD-PRODUCTION QUALITY

B01

TYPE APPROVAL COUNTRY GERMANY

C7R

ALLOY WHEELS 7.5J X 17

E0A

NO SPECIAL EDITION

ER1

REGIONAL CODE " ECE " FOR RADIO

F0A

NO SPECIAL PURPOSE VEHICLE, STANDARD EQUIPMENT

FK2

WITH ADDITIONAL TANK FOR SCR (24 LITERS)

FQ0

PRODUCTION WHEELS

FZ1

N.N.N. TYPE 1

GB1

BOOSTER TYPE 1

GP1

VEHICLES WITH SPECIAL UPGRADE MEASURES

H0B

TIRES 225/50 R17 94Y

IU1

WITH CONNECT PACKAGE 1

IX2

DIESEL ENGINE

A51

AUDI AG

A9F

"ATTRACTION" EQUIPMENT

AV1

DRIVING ON THE RIGHT

B0A

COMPONENT PARTS SET WITHOUT COUNTRY-SPECIFIC BUILDING REGULATION

D95

4-CYL. TURBO DIESEL ENGINE 2.0 L/120 KW 4V TDI COMMON RAIL, BASE ENGINE IS TG3/TH3/TL4/TM4/TD1/T6F/T6M

EA0

WITHOUT FOLLOW-ON WARRANTY

EW0

WITHOUT MAINTENANCE CONTRACT

FA0

CONTROL OF SERIES PRODUCTION

FM0

BASIC EQUIPMENT VARIANT

FU0

COUNTRY GROUP A

G1C

SEVEN-SPEED AUTOMATIC TRANSMISSION

GH0

WITHOUT REAR DIFFERENTIAL

GT6

PLASTIC DECORATIVE INSERTS, HIGH GLOSS

IT3

WITH CONNECT PACKAGE 3

IW3

EMERGENCY CALL SERVICE AND ROADSIDE ASSISTANCE CALL

J2D

BATTERY 380 A (68 AH)

K8D

WAGON/AVANT

KK3

REFRIGERANT R1234YF

L0L

LEFT-HAND DRIVE

NM1

ENGINE COVER

NY0

STANDARD BATTERY/ALTERNATOR CAPACITY

QE1

STORAGE COMPARTMENT PACKAGE 1

QK1

WITH MULTIFUNCTION CAMERA

QQ2

WITH ADDITIONAL LIGHTS (INTERIOR LIGHTING)

QV3

DIGITAL RADIO RECEPTION

S2S

CONTROL (IN-PLANT)

T98

4-CYLINDER DIESEL ENGINE 2.0 L UNIT 05L.A

UH2

PARKING BRAKE

VC0

WITHOUT REMOTE-CONTROLLED GARAGE DOOR
OPENER

VH0

STANDARD ELECTRIC

VT5

SCUFF PLATES IN DOOR APERTURES

KA6

WITH FRONT AND REAR VIEW CAMERA SYSTEM AND
TWO SIDE CAMERAS

KS1

HEAD-UP DISPLAY

N7K

SEAT TRIM COVERS IN ALCANTARA/LEATHER

NT0

TRANSIT COATING (TYPE 1)

Q1D

SPORTS SEATS IN FRONT

QI6

SERVICE INDICATOR 30 000 KM OR 2 YEARS (VARIABLE)

QL5

DARK TINTED GLASS IN REAR SEAT AREA (VENUS
35/PRIVACY) HEAT-INSULATING GLASS (GREEN) IN
FRONT

QR9

WITH DYNAMIC ROAD SIGN DISPLAY

QZ7

POWER STEERING

S3Y

2-DOOR GTI FOR HONG KONG

U5A

INSTRUMENT CLUSTER, KM/H SPEEDOMETER

V0A

TIRES WITHOUT SPECIFICATION OF TIRE BRAND

VF1

PEDAL CLUSTER

VL1

EXTENDED PEDESTRIAN PROTECTION MEASURES

X0A

EQUIPMENT OPTIONS SUBSET FOR GERMANY



+36

Джерела даних
Ми перевірили 900+ джерел даних у **40 країнах**